

Historical Railways Estate

Structure Reference

EDE/25

Public Risk

Severity

High

3

Likelihood

Medium

2

Based On

Arch defects identified in 2020.

Listed?

Yes No

0

Maintenance Req'd?

Essential (< 1 year)

3

Based On

Open joints and downward displacement of arch since 2017 DE.

Future Plans

No plans or proposals

0

Public Access

Subtotal

9

Vandalism

Unlikely problem site

1

Flytipping

No evidence

1

Right of Way

No sign of use

1

Fencing

Good

1

Action/Notes

Total

1

Bridge has been infilled (since exam date) dealing with previously identified movement of arch.
No further action.