



Historical Railways Estate Detailed Examination Report



Line: EDEN VALLEY JCT KIRKBY STEPHEN {WARCOP} No. of Spans 1	Type of Structure: OVERBRIDGE Carrying: PUBLIC ROAD Over: DISMANTLED RAILWAY Name: GREAT MUSGRAVE	ELR: EDE Structure No: OB 25 Mileage: 0m 0000ch Exam. Date: 29/08/2017
---	---	---

Name of Part:	G - Good F - Fair P - Poor	Structure Ref: 3878	Sheet 1 of 83
---------------	----------------------------------	----------------------------	----------------------

Rail Deck Floor	-
Cross Girders	-
Parapet Main Girders C.I.	-
Brick Jack Arches	-
Rivets and Bolts	-
Arch Rings	F
Spandrels	F
Abutments	F
Piers	-
Wing Walls	F
Parapets & Pilasters	F
Columns and Cylinders	-
Buttresses	-
Springer Course	F
String Course	F
Pointing	F
Waterproofing	N/E
Drainage	F
Rubble & Rubbish	-
Fencing/walling	F
Painting	-
Road Condition	F
Vegetation	P
Foundations	N/E
Bridge Numbers	G



General Comments: STRUCTURE IN FAIR CONDITION {Attention to the waterproofing} Weather conditions during the detailed examination - Sunny intervals. Examined by:	Tick as appropriate:	
	Operational Rail Line	
	Canal & River Trust	
	Traffic Management	
	Road Closure	
	Height Restriction Plates	
	Weight Restriction Plates	
	Inaccessible Parts	✓
	Existing Datals / Avongards on Structure	
	Plumbing Points	
	Parapet Risk Assessment	✓
	Underwater Examination carried out during DE	
	Vegetation removed during DE <10%	✓
	Non - Dedication plates	